

Vertical Shaft Impact Crusher Replacement Parts:

CANICA

- **Model 45**

Shoe: 4505
Anvil: 6509
Feed Disc: 4506
Edge Liner: 4504

- **Model 65**

Shoe: 6512
Anvil: 6509
Table Liner: 6511 (0138S)
Edge Liner: 6503
LidLiners: 6504, 6505
Feed Disc: 6510

- **Model L80**

Shoes: ER50 (0811S), ER24
Anvil: 8505 (0312S)
Edge Liner: 8509 (0162S)
Table Liner: 8511 (0130S)
Feed Disc: 8512 (0148S)
Lid Liners: ER36B (0530S),
ER36C (0512),ER36D (0510)

- **Model 95**

Shoe: ER50 (0118S), ER24
Anvil: CA2
Edge Liner: CA9

- **Model 100/125**

Shoe: CA17
Anvils: 9310A, 9311, 9314, CA2
Slinger: 9114
Edge Liner: CA9

IMPACT SERVICES (ISC)

- **77 Series**

Shoes: 8014A, 8014D
Anvils: 8310A, 8317
Feed Disc: 9141
Edge Liner: 9162

CEMCO

- **Model 35**

Anvil: 3402

- **Model 70**

Shoe: 302
Anvil: 402

- **Model 96**

Shoe: 8302
Anvil: 8402

- **Model 54**

Shoe: 302
Feed Disc: 301
Liners: 304, 415, 417, 504
Edge Liners: 307, 308

TORNADO

4113 Shoe
4113X Shoe
C100C Anvil
C94C Anvil
C96C Feed Disc
C970 Table Liner

THE PEARCE GROUP, INC:

16161 Airline Hwy. Prairieville, LA
Toll Free: 1-800-264-1790
Local: (225) 673-6188
Fax: (225) 673-8106
Web: www.pearceusa.com
Email: info@pearceusa.com

